

2nd November 2016

SLV5-53 OBSOLESCENCE

Dear Valued Distributors,

Liquip wishes to advise all distributors that the SLV5-53 plastic housing diaphragm will be made obsolete once current stock is depleted.

PLEASE NOTE

We currently have minimal stock remaining. Presently, customers who have an older SLV5-AO can replace the air diaphragm housing with the SLV5-53.

Once this part transitions into obsolescence, customers will still be able to rebuild foot valves provided the air ram diaphragm is intact. This can be done by purchasing the 3095 diaphragm.

However, if the plastic housing is broken you will have to install the ARO100 (Air Ram) which is a direct replacement.

If you have any questions relating to this bulletin, please contact your local Liquip Representative for further information.

Sincerely,

Liquip



SLV5-53



3095



ARO100

T +61 2 9725 9000 | E: orders@liquip.com | W: liquip.com

www.liquip.com

Liquip International Pty Ltd
ABN 63 112 087 448
13 Hume Road Smithfield, NSW 2164 Australia
PO Box 7049 Wetherill Park, BC NSW 2164
T: +61 2 9725 9000

ONE COMPANY. ONE WORLD. ONE SOURCE.™

